



SKYLIGHT T.G. MINUTES

Recording Sec: Peter Lyons

* Site-Built U-factor test:

Curb-mounted product attached to 2"x4" curb

- Code requirements becoming more stringent whereas product is technology-limited
- Will skylights before too long fail to meet the new Energy Star U-factor of 0.50 in northern climates?
- To make progress, need to make decisions about type of curb & field conditions (eg. location of flashing).
- Mike Thoman said that flashing "can make a huge difference".
- Simulations & tests should include flashings & other detail without which the skylight cannot be installed
- 2"x6" & 2"x8" curbs are ~~the~~ the reality, not 2"x4".
- Willie suggested we may need to test & simulate for worst case, if curb is integral part of product.
- TG members to review minutes & devise plan "soon".